
7 6	APPLIANCE INLET CASING SCREW TERM.50 ² -70 ² EA/PH 4P+E	1 899.SP2FE70S	26
-	CRIMPING TERM.95 ² EARTH	899.SP2FE95	30
5	SCREW TERM.50 ² -70 ² PHASE CRIMPING TERM.95 ² PHASE	899.SP2SC70 899.SP2CP95	2630
4	SHORT INSERT (PLUG) 3P+E	899.SP2CP95 899.SP2PI3 1	JU
3	FEMALE PHASE CAL.10	899.SP2FC10 3	
2	MALE EARTH CONTACT CAL.10	899.SP2ME10 1	
1	MALE PILOT PIN CRIMP CAL.6	899.SP2MP06 2	9
Ind	Description	Reference Cont.	Strip. A



PRODUCT REFERENCE



899.AS2AR350V 899.AS2AR370 899.AS2AR395 ASSEMBLY INSTRUCTIONS

1- PREPARE THE CABLES AS SCHEME BELOW.

2- CRIMP OR SOLDER CABLE TERMINALS (5;6) ON PHASE CABLES AND EARTH CABLE [TOOL Nr 6 AND 7]. FOR CABLE TERMINALS TO SCREW [TOOL Nr 4].

3- UNSCREW PLATE (7.2) [TOOL Nr 3].

4- SLIDE SEAL (7.1) AND PLATE (7.2) OVER THE CABLE.

5- ENGAGE EARTH CONTACT (2) IN THE HOLE OF EARTH EAR IN THE MIDDLE OF INLET CASING (7).

6- PLACE CABLE TERMINAL (6) OF EARTH CABLE AT THE BACKSIDE OF EARTH CONTACT (2), SCREW CONTACT, WHEN CABLE TERMINAL HEXAGON TOUCH EARTH EAR OF INLET CASING (7), PUSH IT INSIDE OF EARTH EAR TO BLOCK IT, THEN TIGHTEN CONTACT (2) (TORQUE 4Nm) [TOOL Nr 1 AND 2].

7- REMOVE SCREWS OF CONTACTS (1) [TOOL Nr 5], INTRODUCE. INTRODUCE PILOT CABLE IN BACKSIDE OF INSERT (4) TO GO OUT IN FRONT. CRIMP CONTACTS (1) ON CABLE [TOOL Nr 8] INTRODUCE CONTACTS (1) IN INSERT (4) TIGHTEN SCREW ON CANTACT (1) [TOOL Nr 1].

8- INTRODUCE EACH CABLE TERMINAL (5) AT THE BACKSIDE OF FEMALE CONTACT CARRIER (4), HEXAGON OF CABLE TERMINAL MUST CORRESPOND WITH HEXAGON INSIDE OF THE FEMALE CONTACT CARRIER, THEN SCREW CONTACTS (3) IN THE FRONT OF FEMALE CONTACT CARRIER (TORQUE 4Nm) [TOOL Nr 1 AND 2].

9- INTRODUCE INSERT (4) IN INLET CASING (7) AND FIX PLATE (7.2) [TOOL Nr 3]. DO NOT FORGET PLACE NUT (7.3) BETWEEN PLATE (7.2) AND INLET CASING (7).

10- SEAL (7.1) AT THE BACKSIDE OF PLATE (7.2).

LIST OF TOOLS *

1- TORQUE WRENCH FACOM REF. J.306A50

2- SOCKETS FACOM : 3/8" Nr14 REF: J.14LA

3- ANGLED SOCKET WRENCH OR OPEN END WRENCH 10mm


4- ALLEN KEY Nr3

Nr4

- 5- FLAT SCREWDRIVER Nr 3
- 6- CRIMPING TOOL KLAUKE HK 120 U

7- KLAUKE CRIMPING JAW: 95² REF: HNFF 13/95

8-CRIMPING TOOL CEMBRE HN1



* TOOL REFERENCES ARE ONLY RECOMMENDED AND GIVEN AS EXAMPLES. TOOLS ARE NOT PROVIDED OR IMPOSED BY SCAME.

7), PUSH IT INSIDE OF EARTH EAR TO BLOCK IT, 8] INTRODUCE CONTACTS (1) IN INSERT (4) TIGHTEN 1ALE CONTACT CARRIER, THEN SCREW



S.p.A. PARRE - (Bergamo) zp90982-26-2_mp39415